


<u>Fig. 1</u>






Fig. 4

<u>LME</u>	CS L Bit	CS D Bit	Operating Mode	
0	x	0	16 Bit Mode	
0	х	1	32 Bit Mode	
1	0	0	16 Bit Compatibility Mode	
1	0	1	32 Bit Compatibility Mode	
1	1	0	32/64 Mode	
1	1	1	Reserved	

70

Fig. 5

Number of Overrio (66H Operand, 67H	0	1	2+	
22/(43/4.1.	Operand Size	32 bits	64 bits	16 bits
32/64 Mode	Address Size	64 bits	32 bits	32 bits
32 Bit Mode Incl.	Operand Size	32 bits	16 bits	16 bits
Compatibility Mode	Address Size	32 bits	16 bits	16 bits
16 Bit Mode Incl.	Operand Size	16 bits	32 bits	32 bits
Compatibility Mode	Address Size	16 bits	32 bits	32 bits

72

Fig. 6




Fig. 7





Fig. 8

SCHIES FORMOTOS



140

Fig. 10




Fig. 11

iiinifii filfafiii

